

Certificate no.:
ABS REP-60-432 -2017-IT

Project no.:
N/A

Report date:
14/08/2017

Office:
Curno, Italy

Independent Third Party Inspection Certificate

| Dati Fabbricante / Manufacturer identification | | |
|--|---|--------------------------------|
| Sede Legale / Unità Operativa Head Office / Plant | FLV – Flour Valve Srl VIA FAUSTO COPPI 5 VERDERIO(LC) CAP 23879 | |
| Dati Prodotto / Product identification | | |
| Tipologia / Type: | BALL VALVE 2" ANSI 150 | |
| Valve Body/ Terminal Material: | ASTM A105N | |
| Ball Material: | ASTM A105N + E.N.P. | |
| Stem Material: | ASTM A182 F6A | |
| Seat Material: | ASTM A105N + E.N.P./ PTFE | |
| Stud & Nuts Material: | ASTM A 193 B7 – ASTM A 194 2H | |
| Denominazione/ Denomination | Marchio / Trademark: | 2" #150 S/N: 17115001 |
| | Modelli / Models: | BALL TRUNNION VALVE SIDE ENTRY |
| Norma di riferimento Reference standard | Prova / Test | Risultato / Result |
| ISO 10497-2010 API 607 | Fire Safe Test | Satisfactory |
| Altre Informazioni / Other Information | | |
| Laboratorio di prova: Test location: | Internal Testing | |
| Test Report No.: | R006/033/2017 | |
| Allegati / Annexes : | Fire Safe Test Report | |

Statement prepared and submitted without prejudice by:

Technical Representative
ABS Group LTD



This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and the liability of ABS Services Ltd. (hereinafter referred to as ABS Services) shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall ABS Services be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by ABS Services and which are covered by this Report.