

Certificate no.: ABS REP-60-431/A -2017-IT Project no. N/A Report date: 14/08/2017

Office: Curno, Italy

Dati Fabbricante / Man			
Sede Legale / Unità Operativa	FLV – Flour Valve Srl VIA FAUSTO COPPI 5 VERDERIO(LC) CAP 23879		
Head Office / Plant			
Dati Prodotto / Product	identification		
Tipologia / Type:	BALL VALVE 4" ANSI 150		
Valve Body/ Terminal Material:	ASTM A105N		
Ball Material:	ASTM A105N + E.N.P.		
Stem Material:	ASTM A182 F6A		
Seat Material:	ASTM A105N + E.N.P./ PTFE		
Stud & Nuts Material:	ASTM A 193 B7 – ASTM A 194 2H		2H
Denominazione/ Denomination	Marchio / Trademark:	4" #150 S/N: 17115003	
	Modelli / Models:	BALL TRUNNION VALVE SIDE ENTRY	
Norma di riferimento Reference standard	Prova / Test		Risultato / Result
ISO 10497-2010 API 607	Fire Safe Test		Satisfactory
Altre Informazioni / Oth	ner Information		
Laboratorio di prova: Test location:	Internal Testing		
Test Report No.:	R005/033/2017		
Allegati / Annexes :	Fire Safe Test Report		

**Independent Third Party Inspection Certificate** 

Statement prepared and submitted without prejudice by:

Technical Representative

ABS Group LTD

This Report is granted subject to the condition that it is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied and the liability of ABS Services Ltd. (hereinafter referred to as ABS Services) shall be limited to the acts or omissions of its employees, agents or subcontractors. Under no circumstances whatsoever shall ABS Services be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by ABS Services and which are covered by this Report.